

Napier

Denonoe

1839

McGILL UNIVERSITY
ARCHIVES
ACC. NO. 221111
REF. 17

Down an Starboard Side

Above & Right-hand

| | | | Sound |
|----|-----|--------------------------|------------------|
| | Bow | Aunt | do |
| 1 | do | Bow - Bow | do |
| 2 | do | 12 feet from the Capstan | partially rotten |
| 3 | do | 4 feet further on | do |
| 4 | do | 5 feet | do |
| 5 | do | 5 feet | do |
| 6 | do | after part fore chains | do |
| 7 | do | 10 feet further on | do |
| 8 | do | 10 feet | do |
| 9 | do | fore part main chains | do |
| 10 | do | Middle of do | do |
| 11 | do | after part of do | partially rotten |
| 12 | do | 6 feet further aft | do |
| 13 | do | 6 feet further aft | do |
| 14 | do | upper & lower transom | do |
| | | Deck & fashion piece | do |
| | | Starboard | do |
| | | 2 joists below Mast part | do |

Starboard Side

| | | | |
|----|----|---|-------------------|
| 1 | do | 10 feet from fashion piece floor head below the above | do |
| 2 | do | 6 feet further on | do |
| 3 | do | after part of Mc Chain | do |
| 4 | do | fore part | do |
| 5 | do | 10 feet further from do | do |
| 6 | do | 10 feet | do |
| 7 | do | 5 feet | do |
| 8 | do | after part of fore chains | partially decayed |
| 9 | do | fore part | do |
| 10 | do | aboard the foremast | do |
| | | foremast beam | rotten |
| | | 3 rd Breast hook | partially |
| | | the others | rotten |
| | | foremast beam | do |
| | | fore part of the beam | partially |
| | | two foremast parrels | rotten |
| | | | do |

